

Seismic performance of RC low-rise building structures having irregularities at the ground story during the 15 November 2017 Korea earthquake

Kyung-Ran Hwang and Han-Seon Lee School of Civil, Environmental, and Architectural Engineering, Korea University


Introduction

This poster presents seismic failure of RC low-rise building structures having irregularities at the ground story during the 15 November 2017 Pohang earthquake, M_w =5.4, which is the second strongest since the government began monitoring them in 1978 in South Korea. This earthquake caused serious damage at the piloti story of RC low-rise building structures within the epicenter distance of 3km with a brittle shear failure of columns and walls due to severe torsional behavior.





H school: 3-story RC MRF structure




C building: 4-story RC piloti-type bldg. structure




K building: 4-story RC wall building structure



In a shear wall in the horizontal direction, serious shear failure occurred. The wall is not placed in the center of the plan. Because of this torsional irregularity, many cracks in the wall in the transverse direction are observed, despite a large amount of wall in the transverse direction.








F building: 5-story RC piloti-type bldg. structure







300mm) = **152mm**

Conclusions

- After the 2017 Pohang earthquake (M_w=5.4), some 2,000 private houses were damaged or destroyed. A large number of the houses are RC low-rise building structures (less than five-story) having a high torsional irregularity.
- Before 2005, buildings below six stories did not have to satisfy the seismic design requirement.
- The earthquake caused unexpected brittle shear failures in columns on the flexible side of RC low-rise piloti-type building structures having torsional irregularity.
- Confinement detailing of columns and walls apparently led to inadequate performance.
- A building plan orientation of damaged structural element appears to be consistent with the horizontal component N-S of the ground motion.
- Appropriateness of torsion design approaches in the current code should be examined.

ACKNOWLEDGMENTS

The research presented herein was supported by the National Research Foundation of Korea (NRF-2009-0078771, NRF-2016R1C1B1016653, and NRF-2017R1D1A1B03033488). The authors are grateful for these supports.

