

UCB-BYU-UCLA  
ZETAŞ-SAU  
Joint Research

**Project Name:** Ground Failure and Building Performance in Adapazari, Turkey  
**Location:** Site J - Çırak Street, Yenigün District, Adapazari  
**GPS Coordinates:** 40.77518°N 30.41077°E  
**Test Number:** CPT-J2  
**Type of Cone:** ELC10 CFPS No. 991232 (a.p. v.d. Berg)

Page: 1 of 3

**Elevation:** 0 cm with respect to CPT-J2

**Date:** June 19, 2000

Sponsored by:

NSF, PEER

**File Name:** cptj2.txt


**Operator:** ZETAŞ (Zemin Teknolojisi, A. Ş.)

**Water Table Elevation:** Not measured

**Responsible Engineers:** J. D. Bray and R. B. Sancio, U. C. Berkeley

Caltrans, CEC, PG&E

**Notes:**



UCB-BYU-UCLA  
ZETAŞ-SAU  
Joint Research

**Project Name:** Ground Failure and Building Performance in Adapazari, Turkey  
**Location:** Site J - Çırak Street, Yenigün District, Adapazari  
**GPS Coordinates:** 40.77518°N 30.41077°E  
**Test Number:** CPT-J2  
**Type of Cone:** ELC10 CFPS No. 991232 (a.p. v.d. Berg)

Page: 2 of 3

**Elevation:** 0 cm with respect to CPT-J2

**Date:** June 19, 2000

**Water Table Elevation:** Not measured

**Responsible Engineers:** J. D. Bray and R. B. Sancio, U. C. Berkeley

Sponsored by:


NSF, PEER

Caltrans, CEC, PG&E

**File Name:** cptj2.txt

**Operator:** ZETAŞ (Zemin Teknolojisi, A. Ş.)

**Notes:**



UCB-BYU-UCLA  
ZETAŞ-SAU  
Joint Research

**Project Name:** Ground Failure and Building Performance in Adapazari, Turkey  
**Location:** Site J - Çırak Street, Yenigün District, Adapazari  
**GPS Coordinates:** 40.77518°N 30.41077°E  
**Test Number:** CPT-J2  
**Type of Cone:** ELC10 CFPS No. 991232 (a.p. v.d. Berg)

Page: 3 of 3

**Elevation:** 0 cm with respect to CPT-J2

**Date:** June 19, 2000

Sponsored by:

NSF, PEER

**File Name:** cptj2.txt

**Operator:** ZETAŞ (Zemin Teknolojisi, A. Ş.)

**Water Table Elevation:** Not measured

**Responsible Engineers:** J. D. Bray and R. B. Sancio, U. C. Berkeley

Caltrans, CEC, PG&E

**Notes:**

