

A (Brief) Survey of Structures Affected by Surface Fault Rupture

PEER SURFACE FAULT DISPLACEMENT HAZARD WORKSHOP

U.C. Berkeley

May 20-21, 2009

Timothy Dawson

California Geological Survey



Cal Memorial Stadium



Chelungpu fault

Hector Mine EQ vs. Future Urban Earthquake





Photo by Bill Bryant



Offset Roads



Fault crossing Richardson Highway.
Right-lateral offset was about 3.9m at this
location

Photo by Tim Dawson

Damaged Power Transmission Tower



Photo by Tim Dawson

Offset Railroads



Photo by Aykut Barka

1999 Izmit



Photo by Tim Dawson

Offset Bridge



1999 Duzce EQ Bolu Viaduct



Shihkang Dam – 1999 Taiwan



Photo from Geo-engineering Extreme Events Reconnaissance (GEER) website :
[http://Geo-engineering research.eerc.berkeley.edu/projects/GEER/GEER_Post%20EQ%20Reports/Chi-Chi_1999/aerial_taiwan.htm](http://Geo-engineering%20research.eerc.berkeley.edu/projects/GEER/GEER_Post%20EQ%20Reports/Chi-Chi_1999/aerial_taiwan.htm)

2002 Denali Earthquake – Trans-Alaska Pipeline



Photo by Rob Kayen

