


Difference in elevation with respect to CPT-B3	
CPT-B1	-20 cm
CPT-B2	-31 cm
CPT-B3	0.0 cm
CPT-B4	-29 cm
SPT-B1	-22 cm
SPT-B2	-14 cm
Point 1 on Kuyudibi Avenue sidewalk	-07 cm

KUYUDiBi Avenue



UCB-BYU-UCLA-ZETAS-SAU Joint Research Sponsored by: NSF-PEER-Caltrans-CEC-PG&E	
Project: Ground Failure and Building Performance in Adapazari, Turkey Responsible Engineers: J.D. Bray and R.B. Sancio, U.C. Berkeley	
Contents: Plan view of Site B and location of subsurface exploration points	
Location: Kuyudibi Avenue, Karaosman District, Adapazari GPS Coordinates: 40.78513° N 30.40024° E	
Scale: Graphic Scale	File Name: site_b.fcw - site_b.pdf
Date: 10/23/00	Drawing: Rodolfo B. Sancio